EAST Search History

Ref#	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	7	187/314.ccls. and (ceiling roof) near8 (hatch escape opening passage\$1way passage portal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:42
L2	0	WO-200000228-\$.did.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:49
_3	0	WO-2000000228-\$.did.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:49
_4	1	2000WO-CH00228.ap,prai.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:50
_8	4	187/393.ccls. and (ceiling roof) near8 (hatch escape opening passage\$1way passage portal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:03
_9	11	454/68.ccls. and (ceiling roof) near8 (hatch escape opening passage\$1way passage portal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:03
_10	13	8 9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:03
L11	1	("2398627").URPN.	USPAT	OR	ON	2008/03/17 03:04
_12	4	("2350389").URPN.	USPAT	OR	ON	2008/03/17 03:05
_13	2	49/507.ccls. and (ceiling roof) near8 (hatch escape opening passage\$1way passage portal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:15
_14	1330	"49".clas. and (ceiling roof) near8 (hatch escape opening passage\$1way passage portal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:15
_15	317	14 and (suspen\$4 support\$3) near10 (panel sheet)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:16
_16	73	15 and (track rail elongat\$3 rectilinea\$3) near10 (slot adjust \$4 recess passage\$1way passage)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:18
_17	228	14 and (suspen\$4 support\$3) with ((panel sheet) and (roof ceiling))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:18
_18	183	17 not 16	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:20

L19	22	("2568355" "2722272" "2799890" "2821895" "3232205" "3792511" "3858355" "3964377" "4287815" "4469018" "4483102" "4502368" "4520715").PN. OR ("4735132"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 03:23
L20	26	("2380782" "2802410" "2834278" "3130659" "4026082"). PN. OR ("4502368").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 03:25
L21	13	("1539312" "4151894" "4185433" "4502368" "4563845" "4567074" "4581861" "4658555" "6014841" "6269597"). PN. OR ("6601352").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 03:26
L22	1775	52/202,19.ccls. 24/580.1.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ÖN	2008/03/17 03:28
L23	112	22 and (suspen\$4 support\$3 secur\$3 fasten\$3) with ((panel sheet) and (roof ceiling))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:29
L24	134	22 and (ceiling roof) near8 (hatch escape opening passage \$1way passage portal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:31
L25	59	24 not 23	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:31
L26	5166	B66B013/02.ipc. B66B011/02.ipc. B66B007/00.ipc.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:42
L27	99	26 and (ceiling roof) near8 (hatch escape opening passage \$1way passage portal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:43
L28	6	27 and (suspen\$4 support\$3 secur\$3 fasten\$3 hang\$3) with ((panel sheet) and (roof ceiling))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:43
L29	93	27 not 28	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 03:44
S1	43	(("4361208") or ("6142260") or ("5659160") or ("5701973") or ("5862889") or ("6830355") or ("20040136199") or ("5802766") or ("5808541") or ("4630423") or ("4897992") or ("5337525") or ("5609225") or ("7220023") or ("20040262094") or ("4789049") or ("5509209") or ("4915438") or ("5797657") or ("5636383") or ("4265353") or ("7165649") or ("20050029042") or ("3631942") or ("4176732") or ("4357993") or ("4430835") or ("4462193") or ("4570754") or ("4779707") or ("4875552") or ("4875553") or ("4890200") or ("5003432") or ("5354233") or ("5408394") or ("5593347") or ("5699437") or ("5306208")).PN.	US-PGPUB; USPAT	OR	OFF	2008/03/17 00:52
S2	57	187/401,414.ccls. and (ceiling roof) near8 (hatch escape opening passage\$1way passage)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 01:21
S3	10	("1925417" "4635756" "4699251" "4984406" "5404686" "5433047" "5842545").PN. OR ("6082501").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 01:23
S4	19	("2019379" "3481094" "3813839" "4126210" "4164011" "4223503" "4283897" "4357993" "4425603" "4529062" "4557086").PN. OR ("4699251").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 01:23
S5	26	("0667603" "1277319" "1809508" "2128797" "2753390" "2834064" "3810341" "3902280").PN. OR ("4357993"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 01:24

S6	22	("2133621" "2343201" "3113358" "3327440" "3529394" "3631942" "3632146" "4199907" "4357993" "4479737" "4566237").PN. OR ("4875552").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 01:25
S7	16	("2680502" "3035165" "3328576" "3631942").PN. OR ("4126210").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 01:29
S8	203	52/282.4,365,506.03,506.04,506.06,506.08.ccls. and (ceiling roof) near8 (hatch escape opening passage\$1way passage)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 01:35
S9	202	S8 not (S1 S2 S3 S4 S5 S6 S7)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 01:35
S10	6	("3175656").URPN.	USPAT	OR	ON	2008/03/17 01:51
S11	65	("0868382" "1039647" "1939115" "2114044" "2143034" "2178817" "2242461" "2867013" "2947093" "2967309" "3008249" "3098240" "3283340" "3458963" "3591997" "3667177" "3775926" "3831334" "3834782" "3873151" "3991537" "4009903" "4040223" "4087127" "4196552" "4640076" "4660339" "4671026" "4680817" "4691392" "4736559" "4750624" "5127131").PN. OR ("5337525"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 01:54
S12	86	("20010047971" "20030189019" "2029089" "3192667" "3204776" "3310271" "3469710" "3698565" "3733756" "4223488" "4229913" "4323163" "4420087" "4438604" "4450970" "4572381" "4579308" "4589557" "4591058" "4593824" "4598504" "4602756" "4607753" "4615448" "4629076" "4638618" "4674240" "4877794" "4805783" "4805784" "4809479" "4811475" "4825601" "4826022" "4891897" "4932538" "4944416" "4961295" "5138803" "5142832" "5185971" "5228579" "5241796" "5337525" "5360121" "5375802" "5412912" "5429252" "5477969" "5484067" "5547156" "5582376" "5655674" "5671852" "5697507" "5740927" "5791093" "5819490" "5857577" "5899344" "5941026" "5944203" "6050426" "6068135" "6116435" "6119784" "6119878" "6123154" "6134846" "6164467" "6199705" "6209730" "6276034" "6299001" "6311854" "6325223" "6349507" "6363645" "6591996"). PN. OR ("6945414").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 01:58
S13	35	("2319278" "3005293" "4262465" "4505611" "4765111" "4977717").PN. OR ("5412912").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 02:01
S14	22	52/506.09.ccls. and (ceiling roof) near8 (hatch escape opening passage\$1way passage)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:03
S15	14	S14 not (S8 S9 S10 S11 S12 S13)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:03
S16	86	52/220.8,717.01,718.01.ccls. and (ceiling roof) near8 (hatch escape opening passage\$1way passage)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:09
S17	69	52/220.8.ccls. and (ceiling roof) near8 (hatch escape opening passage\$1way passage)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:13
S18	67	S17 not (S1 S2 S3 S4 S5 S6 S7 S8 S10 S11 S12 S13 S14)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:14
S19	260	248/544,237,221.11,301,323,343.ccls. and (ceiling roof) near8 (hatch escape opening passage\$1way passage)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:22

S20	255	S19 not (S1 S2 S3 S4 S5 S6 S7 S8 S10 S11 S12 S13 S14 S17)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:23
S21	O	S20 and 248/544,237,221.11,301,323,343.ccls. and (ceiling roof) near8 (portal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:23
S22	0	248/544,237,221.11,301,323,343.ccls. and (ceiling roof) near8 (portal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/17 02:24
S23	4	US-5549180-\$.did. US-4699251-\$.did. US-5644111-\$.did. JP-02013590-\$.did.	USPAT; JPO	OR	ON	2008/03/17 02:32
S24	105	("1887209" "1947079" "2109361" "2193609" "2227147" "2417092" "2631273" "2806555" "2900521" "2909767" "3091760" "3168164" "3176797" "3207266" "3370285" "3461422" "3545572" "3605082" "3609730" "3641549" "3644917" "3742222" "3745550" "3746863" "3760397" "3773145" "3816745" "3825745" "3857466" "3903996" "3914753" "4009389" "4052716" "4067416" "4092636" "4108281" "4207466" "4266124" "4326197" "4384280" "4399430" "4460066" "4479053" "4507654" "4520343" "4581526" "4590410" "4644329" "4716992" "4733081" "4742337" "4839631" "4879461" "4893005" "4897630" "4910464" "4942385" "4973837" "4976337" "4987402" "5015840" "5025895" "5053616" "5138150" "5149921" "5202540" "5283400" "5347094" "5443142" "5476157" "5487448" "Re33668").PN. OR ("5644111").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 02:33
S25	16	("1767988" "3653589" "4032828" "4241871" "4751398" "4875553" "4905579" "4977818" "5123875").PN. OR ("5593347").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/17 02:34

3/17/2008 3:53:24 AM

C:\Documents and Settings\skruer\My Documents\EAST\Workspaces\Search - Assistant Ceiling Device for Shielding Escape Hatch - 10581959.wsp